
## WRISTLET WATCH WITH ALARM, shockproof, 20 jewels



Solid lever movement J 89, with alarm, 20 jewels, shockproof. Nivarox hairspring, steel pallet and lever escape wheel, sweep seconds hand

J 89

Plates - 29,4 mm Ø - Illustration twice original size



## WRISTLET WATCH WITH ALARM shockproof, 20 jewels



When the watch is fully wound up, the going time of the watch, after the alarm has run down, yet amounts to more than 30 hours.

For special attention! Should accidents make a repair necessary then it is advisable on refitting the back to observe the following: In order to keep the alarm properly functioning the winding button has to stand upright and the case-pin has to fit into the groove of the back. In doing so the stop button is to be pressed in.

Junghans